

	Republic of the Philippines <b>ILOILO SCIENCE AND TECHNOLOGY UNIVERSITY</b> La Paz, Iloilo City				Department:	<b>BIDS AND AWARDS COMMITTEE</b>																																											
	<b>JOB ORDER</b>				Document Code:	<b>QF-BAC-12</b>																																											
					Rev. No.:	<b>02</b>																																											
					Effective Date:	<b>April 1, 2018</b>																																											
Name of Supplier: <b>JMJ HILADO GLASS AND ALUMINUM SUPPLY</b> J.O. No.: <b>2025-03-040</b>																																																	
Address: <b>Malugsod, Pototan, Iloilo</b> Date: <b>March 31, 2025</b>																																																	
TIN: <b>482-147-723-00000</b> Mode of Procurement: <b>SMALL VALUE PROCUREMENT</b>																																																	
Gentlemen: Please excute/carry out the following job/project subject to the terms and conditions contained herein:																																																	
Project Title: <b>Repair of Student Services Building Glass Partition</b>				Contract Duration:	<b>25 calendar days upon receipt of NTP</b>																																												
Location: <b>Burgos St. Lapaz, Iloilo City</b>				Payment Term:	<b>CHARGE</b>																																												
Item No.	Job/Work Category	Description	Quantity	Unit	Unit Cost	Total Cost																																											
1	Repair and Maintenance	<b>Repair of Student Services Building Glass Partition</b>	1	lot	210,000.00	210,000.00																																											
		<b>Scope of Works</b>																																															
		<table><tr><td>Qty.</td><td>Unit</td><td>Unit Cost</td><td>Amount</td></tr><tr><td colspan="4"><b>I. GENERAL REQUIREMENTS AND SITE WORKS.</b> Include Supply Of Necessary Materials, Labor And Equipment For Repair Of Glass Curtain Wall And Temporary Protective Enclosure For The Staircase From Ground-floor To 4thfloor Includes Overhead Covers, Side Barriers And Warning Signs.</td></tr><tr><td>1</td><td>L.S</td><td>20,000.00</td><td>20,000.00</td></tr><tr><td colspan="4"><b>II. EXISTING CONDITIONS.</b> Includes Dismantling And Repairing The Existing Glass Curtain Wall, Clearing And Hauling Debris, Managing Excess And Salvage Materials, And Transferring Existing Equipment To The Isat U Storage Facility. Replace Defective Brackets And Apply Sealants Or Fasteners To Ensure The WeatherproofingOf The Glass Curtain Wall In The Fourth Floor Area. Additionally, Remove Stains From Glass Panels And Clean The Aluminum Framing From The Ground Floor To The Fourth Floor In The Interior Of The Stair</td></tr><tr><td>A. Dismantling and Repair of Glass Curtain Wall</td><td>1</td><td>L.S</td><td>15,000.00</td><td>15,000.00</td></tr><tr><td>B. Clearing and Hauling</td><td>1</td><td>L.S</td><td>15,000.00</td><td>15,000.00</td></tr><tr><td>C. Cleaning of Glass Panels &amp; Aluminum Framing</td><td>1</td><td>L.S</td><td>15,000.00</td><td>15,000.00</td></tr><tr><td colspan="4"><b>III. GLASS WORKS.</b> Includes Supply of Necessary Materials, Labor and Equipment for Glass Curtain Wall as Specified in the Pow, Boq, Plans and Specifications.includesApplying of Silicone Sealant to All Glass Edges From Ground to 4thfloor Area and Replacement ofBroken Glass Panels at 4th floor Curtain Wall Area.</td></tr><tr><td>65</td><td>SQM</td><td>2,230.76</td><td>145,000.00</td></tr><tr><td colspan="3"><b>Total Cost of Project</b></td><td></td><td><b>210,000.00</b></td></tr></table>	Qty.	Unit	Unit Cost	Amount	<b>I. GENERAL REQUIREMENTS AND SITE WORKS.</b> Include Supply Of Necessary Materials, Labor And Equipment For Repair Of Glass Curtain Wall And Temporary Protective Enclosure For The Staircase From Ground-floor To 4thfloor Includes Overhead Covers, Side Barriers And Warning Signs.				1	L.S	20,000.00	20,000.00	<b>II. EXISTING CONDITIONS.</b> Includes Dismantling And Repairing The Existing Glass Curtain Wall, Clearing And Hauling Debris, Managing Excess And Salvage Materials, And Transferring Existing Equipment To The Isat U Storage Facility. Replace Defective Brackets And Apply Sealants Or Fasteners To Ensure The WeatherproofingOf The Glass Curtain Wall In The Fourth Floor Area. Additionally, Remove Stains From Glass Panels And Clean The Aluminum Framing From The Ground Floor To The Fourth Floor In The Interior Of The Stair				A. Dismantling and Repair of Glass Curtain Wall	1	L.S	15,000.00	15,000.00	B. Clearing and Hauling	1	L.S	15,000.00	15,000.00	C. Cleaning of Glass Panels & Aluminum Framing	1	L.S	15,000.00	15,000.00	<b>III. GLASS WORKS.</b> Includes Supply of Necessary Materials, Labor and Equipment for Glass Curtain Wall as Specified in the Pow, Boq, Plans and Specifications.includesApplying of Silicone Sealant to All Glass Edges From Ground to 4thfloor Area and Replacement ofBroken Glass Panels at 4th floor Curtain Wall Area.				65	SQM	2,230.76	145,000.00	<b>Total Cost of Project</b>				<b>210,000.00</b>			
Qty.	Unit	Unit Cost	Amount																																														
<b>I. GENERAL REQUIREMENTS AND SITE WORKS.</b> Include Supply Of Necessary Materials, Labor And Equipment For Repair Of Glass Curtain Wall And Temporary Protective Enclosure For The Staircase From Ground-floor To 4thfloor Includes Overhead Covers, Side Barriers And Warning Signs.																																																	
1	L.S	20,000.00	20,000.00																																														
<b>II. EXISTING CONDITIONS.</b> Includes Dismantling And Repairing The Existing Glass Curtain Wall, Clearing And Hauling Debris, Managing Excess And Salvage Materials, And Transferring Existing Equipment To The Isat U Storage Facility. Replace Defective Brackets And Apply Sealants Or Fasteners To Ensure The WeatherproofingOf The Glass Curtain Wall In The Fourth Floor Area. Additionally, Remove Stains From Glass Panels And Clean The Aluminum Framing From The Ground Floor To The Fourth Floor In The Interior Of The Stair																																																	
A. Dismantling and Repair of Glass Curtain Wall	1	L.S	15,000.00	15,000.00																																													
B. Clearing and Hauling	1	L.S	15,000.00	15,000.00																																													
C. Cleaning of Glass Panels & Aluminum Framing	1	L.S	15,000.00	15,000.00																																													
<b>III. GLASS WORKS.</b> Includes Supply of Necessary Materials, Labor and Equipment for Glass Curtain Wall as Specified in the Pow, Boq, Plans and Specifications.includesApplying of Silicone Sealant to All Glass Edges From Ground to 4thfloor Area and Replacement ofBroken Glass Panels at 4th floor Curtain Wall Area.																																																	
65	SQM	2,230.76	145,000.00																																														
<b>Total Cost of Project</b>				<b>210,000.00</b>																																													
		<b>Please see attached Program of Works and BOQ</b>																																															
		*****Nothing follows***** For official use of the University. Requested by: Sammy A. Daitao																																															
					Total	210,000.00																																											
<b>Total Amount in Words: TWO HUNDRED TEN THOUSAND PESOS ONLY</b>																																																	
In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent for every day of delay shall be imposed.																																																	
Conforme:																																																	
<b>JMJ HILADO GLASS AND ALUMINUM SUPPLY</b> Supplier April 30, 2025 Date				Very truly yours, <b>GABRIEL M. SALISTRE JR., PhD-DIT</b> University President APR 28 2025 Date																																													
Funds Available:				Checked and Verified by:																																													
<b>JESSICA M. GENZOLA</b> Accountant IV Date				<b>SAMMY A. DAITAO, PhD-TM</b> Director, PDAS Date																																													
				Amount: <b>210,000.00</b> ALOBS No.: <b>2025-04-0101</b>																																													