

# Section VII. Technical Specifications

ITEM NO.	SPECIFICATION		STATEMENT OF COMPLIANCE			
	<b>Procurement of Airconditioning Unit</b>  <b><u>PhP ( 1,844,000.00).</u></b>		[Bidders must state here either "Comply" or "Not Comply" against each of the individual parameters of each Specification stating the corresponding performance parameter of the equipment offered. Statements of "Comply" or "Not Comply" must be supported by evidence in a Bidders Bid and cross-referenced to that evidence. Evidence shall be in the form of manufacturer's un-amended sales literature, unconditional statements of specification and compliance issued by the manufacturer, samples, independent test data etc., as appropriate. A statement that is not supported by evidence or is subsequently found to be contradicted by the evidence presented will render the Bid under evaluation liable for rejection. A statement either in the Bidder's statement of compliance or the supporting evidence that is found to be false either during Bid evaluation, post-qualification or the execution of the Contract may be regarded as fraudulent and render the Bidder or supplier liable for prosecution subject to the applicable laws and issuances.]			
	Specification		UNIT	QTY	BRAND	Statement of Compliance
1	Airconditioning Unit-VPAA-Library	Airconditioning Unit 1.0 HP, 230V, 1 Ph, 60Hz, Split Type Wall Mounted , non inverter - with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	3		
2	Airconditioning Unit-CEA-EE Dept	Airconditioning Unit Non-Inverter 1.0 HP, 230V, 1 Ph, 60Hz, Split Type Wall Mounted with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	3		
3	Airconditioning Unit-CEA-EE Dept	Airconditioning Unit 2.5 HP, 230V, 1 Ph, 60Hz, Split Type Wall Mounted, Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	unit	1		
4	Airconditioning Unit-CEA-ECE Dep	Airconditioning Unit 1.0 HP, 230V, 1 Ph, 60Hz, Split Type, Wall Mounted, Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	8		
5	Airconditioning Unit- CIT-CDDT Dept/Architectural Drafting	Airconditioning Unit 2.5 HP, 230V, 1 Ph, 60Hz, Window Type, Non-inverter with Minimum: EER of 13 kJ/W-h or higher	Unit	3		

		<b>**See attached Site Inspection and Evaluation Report</b>				
6	Airconditioning Unit- VPAA- Medical Clinic	Airconditioning Unit 1.0 HP, 230V, 1 Ph, 60Hz, Split Type, Wall Mounted, Non-inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	unit	2		
7	Airconditioning Unit- VPAA- Medical Clinic	Airconditioning Unit 2.5 HP, 230V, 1 Ph, 60Hz, Split Type, Wall Mounted, Non-inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	4		
8	Airconditioning Unit- VPAA- Cultural Affairs	Airconditioning Unit 2.0 HP, 230V, 1 Ph, 60Hz, Split Type, Wall mounted, Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	1		
9	Airconditioning Unit- VPAA- Cultural Affairs	Airconditioning Unit 1.0 HP, 230V, 1 Ph, 60Hz, Split Type, Wall mounted, Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	unit	2		
10	Airconditioning Unit- CIT- Fashion & Wellness	Airconditioning Unit 1.5HP, 230V, 1 Ph, 60Hz, Split Type wall mounted ,non- Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	2		
11	Airconditioning Unit- IAS	Airconditioning Unit 1.0 HP, 230V, 1 Ph, 60Hz, Split Type, Wall mounted, Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	Unit	1		
12	Airconditioning Unit- CIT- Fashion & Wellness	Airconditioning Unit 3 TR, 230V, 1 Ph, 60Hz, Floor mounted type , non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	unit	1		
13	Airconditioning Unit- VPAA-CAS	Airconditioning Unit	Unit	1		

	F101	3 TR, 230V, 1 Ph, 60Hz, Floor mounted type , Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>				
14	Airconditioning Unit-COA F101	Airconditioning Unit 2.5HP, 230V, 1 Ph, 60Hz, Split Type wall mounted , Non-Inverter with Minimum: EER of 11 kJ/W-h or higher <b>**See attached Site Inspection and Evaluation Report</b>	unit	1		
		<b>**See attached Site Inspection and Evaluation Report</b>				
		<b>Delivery Period: 30 Calendar days Upon Receipt of the NTP</b>				
		<b>Warranty Period 10 years on motor compressor 1 year on parts and services</b>				
		<b>For Equipment: After Sales Services : with Installation and Service Center within locality.</b>				

---



---



---



---